



CONTROLLER PIN OUT

TAB	FUNCTION
1	KSI VOLTAGE
2	THRITTLE THRITTLE
3	THRITTLE REVERSE
4	1/2 SPEED
B+	BATTERY POSITIVE
B-	BATTERY NEGATIVE
M-	MOTOR MINUS

NOTES:

- * FUSES REQUIRED FOR ALL INSTALLATIONS
- * DIODE REQUIRED ACROSS COILS / RELAYS
- * PRE-CHARGE RESISTOR REQUIRED
- > ASSUMES FOOTSWITCH IS OPEN WHEN THRITTLE OFF
- > ALLTRAX RESERVES THE RIGHT TO CHANGE DOCUMENTATION WITHOUT NOTICE
- > ALLTRAX MAKES NO WARRANTY AS TO THE ACCURACY, SUFFICIENCY, OR SUITABILITY OF ANY TECHNICAL OR OTHER INFORMATION PROVIDED
- > SEE OPERATORS MANUAL FOR MORE INFORMATION

* HIGH CURRENT WIRING IN BOLD *

REVISIONS			
REV.	ECO.	DATE	APVD
A	122206	122206	TT
B	090407	090407	RC

DWG SCALE: NTS			
DRAWN	T.Thorne	111306	
ENGR	D.Crockett	111306	

ALLTRAX 1111 Cheney Creek Rd.
Grants Pass, OR 97527
PHONE:(541) 476-5565

PROPRIETARY AND SHALL NOT BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM, WITHOUT THE WRITTEN PERMISSION OF ALLTRAX INC.

FILE: DWG-AXE-EZGO-Wire-Dwg.dwg SHEET 1 of 1